

## 8.2 Spare Parts

## Spare part list welding gun Type P 15

When ordering spare parts, please indicate order number and type of welding gun.

| Pos. | Quantity | Order-No. | Description                              |
|------|----------|-----------|--|
| 1    | 1        | 52-04-05  | Basic shell, complete                    |
| 3    | 1        | 52-03-72  | Covershell                               |
| 5    | 3        | 52-03-73  | Screw EJOT A30 x 8                       |
| 6    | 2        | 52-03-74  | Screw EJOT A30 x 12                      |
| 7    | 1        | 52-02-58  | Micro switch                             |
| 8    | 2        | 52-02-59  | Screw                                    |
| 11   | 1        | 52-03-75  | Trigger complete                         |
| 13   | 1        | 52-03-76  | Cable clamp                              |
| 21   | 1        | 52-03-78  | Piston, complete                         |
| 31   | 1        | 52-03-80  | Pressure spring , contact                |
| 35   | 1        | 52-03-83  | Axial arrest                             |
| 37   | 1        | 52-03-81  | Adjustment piece, spring force, complete |
| 39   | 1        | 52-03-85  | Sticker, spring force                    |
| 41   | 1        | 52-03-82  | End ring                                 |
| 49   | 1        | 52-03-83  | Mains cable complete                     |
| 51   | 1        | 52-02-78  | Antikink bush                            |
| 53   | 11       | 52-02-75  | Cable clamp                              |
| 55   | 1        | 52-02-74  | Cable connector                          |
| 57   | 1        | 52-02-73  | Control cable                            |
| 63   | 1        | 52-03-88  | Connection cable                         |
| 65   | 1        | 38-08-71  | Nut                                      |
| 67   | 3        | 38-08-28  | Washer                                   |
| 69   | 1        | 38-04-45  | Screw, M4 x 12, DIN 912                  |
| 70   | 1        | 52-02-71  | Screw, M4 x 8, DIN 912                   |
| 75   | 1        | 52-03-84  | Sticker, Nelson/P 15                     |
| 76   | 1        | 52-03-95  | Sticker Nelson                           |
| 79   | 1        | 52-02-55  | Bellows                                  |
| 81   | 1        | 52-02-54  | Retaining nut                            |
| 83   | 1        | 52-02-53  | O-ring                                   |
| 87   | 1        | 52-02-51  | Foot ring                                |
| 89   | 3        | 52-02-52  | Screw                                    |
| 91   | 3        | 52-02-50  | Leg                                      |

Welding Type

